

## **Landlord Gas Safety Record**

Cert. No. 2183

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord							
Engineer Redwan El Machachi						Name						Name								
Company							at 1		Company	RR Properties Ltd										
Address			3	32 Hornton Street					Address	138-140										
	Unit 106, Buspace Studios  Conlan Street					Lo	London						Cromwell Road							
	London												London							
	London				Post Code	V	/8 4NR													
Post Code W10 5AP					Tel. No								SW7 4HA							
Tel No. 07940110118											Tel. No	020 7373 3348								
Gas Safe Reg 563836																				
ID Card No. 563836																				
		0																		
Appliance D						Inspection Details														
Location	1	Appliance Type	Make	Mode	el	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combust Reading Ratio CO ppm	con Low Combustion Reading CO2 % Ratio CO CO ppm %	Safety device(s) correct operation	Ventilation Provision satisfactory	Visual condition of flue and termination satisfactory	Flue Performance test	Appliance Serviced	Appliance safe to use		
1 Compartn	nent	Boiler	Potterton	Suprima	80 HE	RS	Yes	Yes	20	22.1		9.00 NA NA NA		NA	Yes	Pass	No	Yes		
2 Living Ro	-	Fire	Gazci	SPND1F		OF	Yes	Yes	20	6.4	0 0			Yes	Yes	Pass	No	Yes		
3																				
4																				
5																				
6																				
Defects / Identified								Labels and Warning Notice Issued			CO Alarm(s)			Smoke	Smoke Alarm(s)					
1										No										
2										No		CO Alarm(s) fit	ted	Yes	Smoke /	Alarm(s) fitt	ed	Yes		
3																				
4											CO Alarm(s) tested				Smoke Alarm(s) tested					
	6										and Satisfacto			ory			d Satisfactory			
U																				
Emergency Co	ntrol Aco	cessible Yes Gas	Tightness Satisfactory Yes		Comn	nents														
Gas Installation	n Pinewo	ork Visual Inspection																		
Number of App			Equipotential Bonding Yes																	
Number of App	Jilalices	resteu Z	Equipotential boliding Tes	)																
NEXT INSPECT	ION DUE	ON OR BEFORE	30-Nov-2019																	
Signatures																				
Issued by:	d	teceived S by:	ceived Signed :							Date 30-Nov-2018										
Print Name		Redwan El Mac	hachi	Р	rint Name															